

TEST REPORT

Swab Test

Date of issue : 10-05-2017
Page 1A of 3

Castco LRN: MB0170426-01

Sample details as supplied by customer:-

Customer: Top Excel (Hong Kong) Ltd.

Address: Room 1504, 15/F., Ricky Centre, 36 Chong Yip Street, Kwun Tong, Kowloon

Job Title: Bacteria Swab Test: "One Year after Application of Maruso Sango M-Clean Photocatalyst Coating" at Civil Aviation Department Headquarter

Date Sampled: 26-04-2017

Contract No.: -

Customer Ref. No.: -

Sampling Certificate attached? Yes; Ref.No.: -- / No

Laboratory Test Result(s):-

Date of sample received: 26-04 2017

Test period: 26-04 to 30-04 2017

Received Condition: Chilled

Reference standard of Test Method

In-House Method MB-AIR-BACTERIA

Remark(s):

- Countable Range: 15-150 CFU, TNTC: Too numerous to count, *:Contain Spreader, #: Estimated Count.
- This test report supersedes previous test report of Castco LRN: MB0170426-1 issued on 02-05-2017.

Checked by :



Horasis Leung
Assistant Technical Manager

Certified by :



LO Tim Lun
Senior Manager

TEST REPORT

Swab Test

Date of issue : 10-05-2017
Page 2A of 3

Castco LRN: MB0170426-01

Related to Castco LRN	Loaction No.	Client ID	Total Bacterial Count (CFU/Swab)
MB0170426-01-42	1	大堂樓梯扶手 (上/右/斜位)	<10
MB0170426-01-43	2	大堂樓梯扶手 (下/右/斜位)	<10
MB0170426-01-36	3	大堂18號電梯控制版	<10
MB0170426-01-37	4	18號電梯控制版 (內部)	<10
MB0170426-01-38	5	1樓19電梯控制版	110
MB0170426-01-13	6	1樓ANC 大門(外/右)	<10
MB0170426-01-12	7	1樓ANC 大門扶手(內/左)	<10
MB0170426-01-32	8	1樓RM125 門扶手 (內/左)	<10
MB0170426-01-31	9	1樓RM125B 門扶手 (外)	10
MB0170426-01-22	10	1樓RM133 門扶手 (外)	<10
MB0170426-01-23	11	1樓RM133B 男更衣室第1間淋浴室門 (內/左)	<10
MB0170426-01-24	12	1樓RM133B 男更衣室第1間淋浴室牆 (左/第4格)	<10
MB0170426-01-25	13	1樓RM133B 男更衣室門 (外)	<10
MB0170426-01-26	14	1樓RM133A 女更衣室門 (外)	<10
MB0170426-01-27	15	1樓RM133A 女更衣室中間淋浴室扶 手 (外)	<10
MB0170426-01-28	16	1樓RM133A 女更衣室中間淋浴室水 龍頭	<10
MB0170426-01-01	17	1樓女洗手間門扶手 (外)	<10
MB0170426-01-29	18	1樓女洗手間A3格門扶手 (外)	10
MB0170426-01-30	19	1樓女洗手間A3格沖水制	10
MB0170426-01-02	23	1樓男洗手間門扶手 (外)	<10
MB0170426-01-03	24	1樓男洗手間內門 (外)	10
MB0170426-01-04	25	1樓男洗手間A2格門扶手 (外)	<10
MB0170426-01-05	26	1樓男洗手間A2格沖水制	<10
MB0170426-01-06	27	1樓男洗手間A2格右邊牆身 (中間)	<10
MB0170426-01-07	28	1樓男洗手間A5格扶手 (外)	<10

Remark:

1. This test report supersedes previous test report of Castco LRN: MB0170426-1 issued on 02-05-2017.

TEST REPORT

Swab Test

Date of issue : 10-05-2017
Page 3A of 3

Castco LRN: MB0170426-01

MB0170426-01-08	29	1樓男洗手間A5格門扶手 (內)	<10
MB0170426-01-09	30	1樓男洗手間A5格沖水制	<10
MB0170426-01-10	31	1樓傷殘洗手間門扶手 (外)	50
MB0170426-01-11	32	1樓傷殘洗手間牆扶手(橫)	60
MB0170426-01-21	33	1樓RM121 門扶手 (外/右)	50
MB0170426-01-34	37	1樓RM106 門扶手 (外/右)	<10
MB0170426-01-33	38	1樓RM106 內門扶手 (內/左)	<10
MB0170426-01-14	39	1樓2號女洗手間門扶手 (外)	<10
MB0170426-01-15	40	1樓女洗手間B1格門扶手 (內)	<10
MB0170426-01-16	41	1樓女洗手間B1格沖水制	<10
MB0170426-01-17	42	1樓2號男洗手間門扶手 (外)	<10
MB0170426-01-18	43	1樓男洗手間B1格門扶手 (內)	10
MB0170426-01-19	44	1樓男洗手間B1格沖水制	<10
MB0170426-01-20	45	1樓RM117 門扶手 (外/左)	10
MB0170426-01-45	46	1樓大樓左則出口門扶手	20
MB0170426-01-39	48	1樓20號電梯控制版 (內/右)	<10
MB0170426-01-40	49	20號電梯地下出口 (內)	<10
MB0170426-01-41	50	20號電梯地下出口斜路扶手 (近細門位置)	<10
MB0170426-01-49	79	2樓男洗手間直門柄 (內)	10
MB0170426-01-50	80	2樓男洗手間A2格沖水制	<10
MB0170426-01-48	81	2樓女洗手間A1格沖水制	<10
MB0170426-01-47	82	2樓電梯灰色門直門柄(外左)	<10
MB0170426-01-44	83	2樓教育徑女洗手間B1格沖水制	<10
MB0170426-01-46	84	2樓教育徑男洗手間B1格沖水制	<10

Remark:

1. This test report supersedes previous test report of Castco LRN: MB0170426-1 issued on 02-05-2017.

End of Report

Form No. ENV AIR_T1 dd 16/11/2008

香港粉嶺安居街33號 33, On Kui Street, Fanling, Hong Kong. Tel : 2597 8333
 香港粉嶺安全街29A號 29A, On Chuen Street, Fanling, Hong Kong. Fax: 2597 8399
 E-mail: info@castco.com.hk Website: www.castco.com.hk

TEST REPORT
Swab TestDate of issue : 10-05-2017
Page 1A of 2

Castco LRN: MB0170427-11

Sample details as supplied by customer:-

Customer: Top Excel (Hong Kong) Ltd.
Address: Room 1504, 15/F., Ricky Centre, 36 Chong Yip Street, Kwun Tong, Kowloon
Job Title: Bacteria Swab Test: "One Year after Application of Maruso Sango M-Clean Photocatalyst Coating" at Civil Aviation Department Headquarter
Date Sampled: 27-04-2017
Contract No.: -
Customer Ref. No.: -
Sampling Certificate attached? Yes; Ref.No.: -- / No

Laboratory Test Result(s):-

Date of sample received: 27-04 2017
Test period: 27-04 to 01-05 2017
Received Condition: Chilled

Reference standard of Test Method

In-House Method MB-AIR-BACTERIA

Remark(s):

- Countable Range: 15-150 CFU, TNTC: Too numerous to count, *:Contain Spreader, #: Estimated Count.
- This test report supersedes previous test report of Castco LRN: MB0170427-11 issued on 02-05-2017.

Checked by :


Horasis Leung
Assistant Technical Manager

Certified by:


LO Tim Lun
Senior Manager

TEST REPORT

Swab Test

Date of issue : 10-05-2017
Page 2A of 2

Castco LRN: MB0170427-11

Related to Castco LRN	Loaction No.	Client ID	Total Bacterial Count (CFU/Swab)
MB0170427-11-01	51	2樓RM205 AIM Cenctre 直門柄(外左)	<10
MB0170427-11-02	52	2樓RM205 內玻璃門柄(內)	<10
MB0170427-11-03	53	205E 門柄(外)	<10
MB0170427-11-04	54	205C 門柄(外)	<10
MB0170427-11-05	55	205B 門柄(外)	10
MB0170427-11-06	56	205A 門柄(外)	10
MB0170427-11-07	57	2樓RM205D 門柄(外)	<10
MB0170427-11-08	58	2樓RM233 RCC直門柄(外左)	10
MB0170427-11-09	59	2/F 大堂玻璃門(外左)	<10
MB0170427-11-10	60	2/F 大堂灰門(出右)	<10
MB0170427-11-11	61	大堂19號電梯2樓控制版	<10
MB0170427-11-12	62	3樓電梯口休息室直門扶手(右外)	<10
MB0170427-11-13	63	天台花園門柄(內)	<10
MB0170427-11-14	64	3樓RM308 門直扶手(外)	<10
MB0170427-11-15	65	3樓RM308 洗手間A1左格沖水制	<10
MB0170427-11-16	66	3樓RM320G 門扶手(外)	<10
MB0170427-11-17	67	3樓RM320G 洗手間A2格沖水制	<10
MB0170427-11-18	68	3樓RM319G 門扶手(外)	<10
MB0170427-11-19	69	3樓RM319洗手間A2右格沖水制	10
MB0170427-11-20	70	3樓RM318 門直扶手(外)	<10
MB0170427-11-21	71	3樓RM318 洗手間A1左格沖水制	20
MB0170427-11-22	72	3樓RM318 洗手間內門扶手 (內)	<10
MB0170427-11-23	73	3樓RM317單 門直扶手(外)	10
MB0170427-11-24	74	3樓RM317女洗手間A1左格沖水制	<10
MB0170427-11-25	75	3樓RM317 女洗手間A2右格沖水制	<10
MB0170427-11-26	76	3樓RM317女更衣室門扶手 (51對面)	20
MB0170427-11-27	77	3樓RM317D 門扶手(外)	<10
MB0170427-11-28	78	3樓RM316男洗手間外門直扶手 (外)	<10
MB0170427-11-29	79	3樓RM316男洗手間內門扶手 (內)	<10
MB0170427-11-30	80	3樓RM316男洗手間A2右格沖水制	<10
MB0170427-11-31	81	3樓RM316男洗手間A1左格沖水制	10
MB0170427-11-32	82	3樓RM316男更衣室門扶手 (54對面/內)	30
MB0170427-11-33	83	3樓RM315主 門直扶手 (內)	<10
MB0170427-11-34	84	3樓RM315洗手間A2右格沖水制	<10
MB0170427-11-35	85	3樓RM315 更衣室門扶手	<10

Remark:

1. This test report supersedes previous test report of Castco LRN: MB0170427-11 issued on 02-05-2017.

End of Report