

Nano-Clear NCI for Industrial - Ammon Painting Restoration & Abatement

Summary of Bridge Testing, MoDOT Chemical Laboratory

Test Panels	Test Conditions	Test Method	Testing Time	Test Results Nano-Clear NCI	Test Results Conventional Topcoat
Coating applied over existing paint system	UV Exposure / Condensation	ASTM G154	2000 hr.	PASS No Weathering Observed	Fail
Coating applied over existing paint system	Salt Fog Exposure / Corrosion Resistance	ASTM B117	2000 hr.	PASS No Weathering or Corrosion Observed	Fail
Coating applied over existing paint system	UV Exposure on MoDOT Laboratory Roof	NONE	4000 hr.	PASS No Weathering Observed	Fail

Kit Bond Bridge - Kansas City, MO



Lewis & Clark Viaduct - Kansas City, MO



